


Application:

Multiple Load Button Load Cells are utilized to measure the tactile force produced by an industrial robot.

Our model TS1 series force sensor can be used for this product.



TS1 series sensors website:

<http://www.gathertechnology.com/Productlist.asp?SortID=80>